

Secure plug connections with cable ties.

Artikel-Nr.: SP41N, SP60
Hersteller: Krömer
EAN-Code: 0757284118791
0738964857155



Problem: Plug connections loosen during operation on the mobile 1-post lift.




Cause: Loose connectors



Solution: Stabilize electrical cable connections to the magnets of the safety catches - to the magnets of the release valve and the limit switches with cable ties.


Page 2

1 Expose connections - if necessary




The relevant connections run below the control panel into the column.

2 Attach cable ties



Secure the connectors by threading zip ties between the electrical wires and clicking together.

3 Secure connections in the column



Push the now secured connectors through the opening in the column.



After securing the connectors, you can safely continue working.